

Gelcoat Repair Kit Instructions:

1. Make sure damaged areas are clean and free of dirt, grease and wax, etc.
2. For large areas/ air voids, mix gel putty with a few drops of hardener to fill holes/cracks.
3. Let sit for one hour, in room temperature.
4. Rinse off excess with soft water
5. Wet sand with 1500-2000 grit until soft.

For minor scratches, use the included gel coat to fill. This is used as a topical treatment.